CONTAINS NO CBI

EPA

Form Approved
OMB No. 2010-0019
Approval Expires 12-31-89

EPA-OTS

000611083J

90-890000511

TOLUENE DIISOCYANATE
CAS 26471- 62- 5

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Comprehensive Assessment Information Rule

REPORTING FORM

When completed, send this form to:	For Agency Use Only:
Document Processing Center Office of Toxic Substances, TS-790 U.S. Environmental Protection Agency 401 M Street, SW Washington, DC 20460 Attention: CAIR Reporting Office	Date of Receipt: _____ Document Control Number: _____ Docket Number: _____

SECTION 1 GENERAL MANUFACTURER, IMPORTER, AND PROCESSOR INFORMATION

PART A GENERAL REPORTING INFORMATION

1.01 This Comprehensive Assessment Information Rule (CAIR) Reporting Form has been completed in response to the Federal Register Notice of..... [1][2] [2][2] [8][8]
mo. day year

CBI

[ ] a. If a Chemical Abstracts Service Number (CAS No.) is provided in the Federal Register, list the CAS No. ..... [0][2][6][4][7][1]-[6][2]-[5]

b. If a chemical substance CAS No. is not provided in the Federal Register, list either (i) the chemical name, (ii) the mixture name, or (iii) the trade name of the chemical substance as provided in the Federal Register.

(i) Chemical name as listed in the rule ..... _____

(ii) Name of mixture as listed in the rule .... _____

(iii) Trade name as listed in the rule ..... _____

c. If a chemical category is provided in the Federal Register, report the name of the category as listed in the rule, the chemical substance CAS No. you are reporting on which falls under the listed category, and the chemical name of the substance you are reporting on which falls under the listed category.

Name of category as listed in the rule ..... _____

CAS No. of chemical substance ..... [ ][ ][ ][ ][ ][ ]-[ ][ ]-[ ]

Name of chemical substance ..... _____

1.02 Identify your reporting status under CAIR by circling the appropriate response(s).

CBI

Manufacturer 1

[ ] Importer 2

Processor ..... (3)

X/P manufacturer reporting for customer who is a processor 4

X/P processor reporting for customer who is a processor 5

[ ] Mark (X) this box if you attach a continuation sheet.

1.03 Does the substance you are reporting on have an "x/p" designation associated with it in the above-listed Federal Register Notice?

CBI

[ ]

Yes ..... [XX] Go to question 1.04

No ..... [ ] Go to question 1.05

1.04 a. Do you manufacture, import, or process the listed substance and distribute it under a trade name(s) different than that listed in the Federal Register Notice? Circle the appropriate response.

CBI

[ ]

Yes ..... As an impurity only 1

No 2

b. Check the appropriate box below:

[ ] You have chosen to notify your customers of their reporting obligations

Provide the trade name(s) .... _____

_____

[ ] You have chosen to report for your customers

[XX] You have submitted the trade name(s) to EPA one day after the effective date of the rule in the Federal Register Notice under which you are reporting.

1.05 If you buy a trade name product and are reporting because you were notified of your reporting requirements by your trade name supplier, provide that trade name.

CBI

[ ]

Trade name ..... N/A

Is the trade name product a mixture? Circle the appropriate response.

Yes ..... N/A 1

No ..... N/A 2

1.06 Certification -- The person who is responsible for the completion of this form must sign the certification statement below:

CBI

[ ]

"I hereby certify that, to the best of my knowledge and belief, all information entered on this form is complete and accurate."

William W. Downey	William W Downey	7/3/89
NAME	SIGNATURE	DATE SIGNED

Plant Manager	(203) 323 - 2159
TITLE	TELEPHONE NO.

[ ] Mark (X) this box if you attach a continuation sheet.

1.07 Exemptions From Reporting -- If you have provided EPA or another Federal agency with the required information on a CAIR Reporting Form for the listed substance within the past 3 years, and this information is current, accurate, and complete for the time period specified in the rule, then sign the certification below. You are required to complete section 1 of this CAIR form and provide any information now required but not previously submitted. Provide a copy of any previous submissions along with your Section 1 submission.

CBI
[ ]

"I hereby certify that, to the best of my knowledge and belief, all required information which I have not included in this CAIR Reporting Form has been submitted to EPA within the past 3 years and is current, accurate, and complete for the time period specified in the rule."

N/A		
NAME	SIGNATURE	DATE SIGNED
N/A	( ) -	
TITLE	TELEPHONE NO.	DATE OF PREVIOUS SUBMISSION

1.08 CBI Certification -- If you have asserted any CBI claims in this report you must certify that the following statements truthfully and accurately apply to all of those confidentiality claims which you have asserted.

CBI
[ ]

"My company has taken measures to protect the confidentiality of the information, and it will continue to take these measures; the information is not, and has not been, reasonably ascertainable by other persons (other than government bodies) by using legitimate means (other than discovery based on a showing of special need in a judicial or quasi-judicial proceeding) without my company's consent; the information is not publicly available elsewhere; and disclosure of the information would cause substantial harm to my company's competitive position."

NAME	SIGNATURE	DATE SIGNED
	( ) -	
TITLE	TELEPHONE NO.	

[ ] Mark (X) this box if you attach a continuation sheet.

PART B CORPORATE DATA

1.09 Facility Identification

CBI Name [A]M]E]R]I]C]A]N]_]C]Y]A]N]A]M]I]D]_]C]O]M]P]A]N]Y]_]

[_] Address [S]H]I]P]P]A]N]_]P]L]A]N]T]_]2]0]5]_]M]A]G]E]E]_]_]
Street

[S]T]A]M]F]O]R]D]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]_]
City

[C]T] [0]6]9]0]2]--[_]_]_]_]
State Zip

Dun & Bradstreet Number ....[1]4]-[0]9]4]-[7]3]4]3]

EPA ID Number ....CTD.....[0]0]0]8]4]4]2]6]5]

Employer ID Number ....13.[0]4]3]0]8]9]0]9]

Primary Standard Industrial Classification (SIC) Code ....[2]8]9]9]

Other SIC Code ....[_]_]_]_]

Other SIC Code ....[_]_]_]_]

1.10 Company Headquarters Identification

CBI Name [A]M]E]R]I]C]A]N]_]C]Y]A]N]A]M]I]D]_]C]O]M]P]A]N]Y]_]

[_] Address [O]N]E]_]C]Y]A]N]A]M]I]D]_]P]L]A]Z]A]_]_]_]_]_]_]_]
Street

[W]A]Y]N]E]_]
City

[N]J] [0]7]4]7]0]--[_]_]_]_]
State Zip

Dun & Bradstreet Number ....[0]0]-[2]1]5]-[0]0]0]1]

Employer ID Number ....13.[0]4]3]0]8]9]0]9]

[_] Mark (X) this box if you attach a continuation sheet.

1.11 Parent Company Identification

CBI Name [ ]

[ ] Address [ ] Street

[ ] City

[ ] State [ ] Zip

Dun & Bradstreet Number .....[ ]-[ ]-[ ]

1.12 Technical Contact

CBI Name [WILLIAM WOWNE]

[ ] Title [PLANT MANAGER]

Address [203 MAGEE AVE] Street

[STANDFORD] City

[CT] State [06902] Zip

Telephone Number .....[203]-[323]-[2160]

1.13 This reporting year is from ..... [01] Mo. [88] Year to [12] Mo. [88] Year

[ ] Mark (X) this box if you attach a continuation sheet.

1.14 Facility Acquired -- If you purchased this facility during the reporting year, provide the following information about the seller:

CBI Name of Seller [ ]

[ ] Mailing Address [ ]
Street

[ ]
City

[ ][ ] [ ][ ][ ][ ][ ]--[ ][ ][ ][ ]
State Zip

Employer ID Number .....[ ][ ][ ][ ][ ][ ][ ][ ]

Date of Sale .....[ ][ ] [ ][ ] [ ][ ]
Mo. Day Year

Contact Person [ ]

Telephone Number .....[ ][ ][ ]-[ ][ ][ ]-[ ][ ][ ][ ]

1.15 Facility Sold -- If you sold this facility during the reporting year, provide the following information about the buyer:

CBI Name of Buyer [ ]

[ ] Mailing Address [ ]
Street

[ ]
City

[ ][ ] [ ][ ][ ][ ][ ]--[ ][ ][ ][ ]
State Zip

Employer ID Number .....[ ][ ][ ][ ][ ][ ][ ][ ]

Date of Purchase .....[ ][ ] [ ][ ] [ ][ ]
Mo. Day Year

Contact Person [ ]

Telephone Number .....[ ][ ][ ]-[ ][ ][ ]-[ ][ ][ ][ ]

[ ] Mark (X) this box if you attach a continuation sheet.

1.16 For each classification listed below, state the quantity of the listed substance that was manufactured, imported, or processed at your facility during the reporting year.

CBI [ ]	Classification	Quantity (kg/yr)
	Manufactured	
	Imported	
	Processed (include quantity repackaged)	6840
	Of that quantity manufactured or imported, report that quantity:	
	In storage at the beginning of the reporting year	
	For on-site use or processing	
	For direct commercial distribution (including export)	
	In storage at the end of the reporting year	
	Of that quantity processed, report that quantity:	
	In storage at the beginning of the reporting year	1536
	Processed as a reactant (chemical producer)	6840
	Processed as a formulation component (mixture producer)	
	Processed as an article component (article producer)	
	Repackaged (including export)	
	In storage at the end of the reporting year	1545

[ ] Mark (X) this box if you attach a continuation sheet.

PART C IDENTIFICATION OF MIXTURES

1.17 Mixture -- If the listed substance on which you are required to report is a mixture or a component of a mixture, provide the following information for each component chemical. (If the mixture composition is variable, report an average percentage of each component chemical for all formulations.)

CBI

[ ] N/A

Component Name	Supplier Name	Average % Composition by Weight (specify precision, e.g., 45% ± 0.5%)
Total		100%

[ ] Mark (X) this box if you attach a continuation sheet.

2.04 State the quantity of the listed substance that your facility manufactured, imported, or processed during the 3 corporate fiscal years preceding the reporting year in descending order.

CBI

[ ] Year ending ..... [1][2] Mo. [8][7] Year

Quantity manufactured ..... 0 kg

Quantity imported ..... 0 kg

Quantity processed ..... 9122 kg

Year ending ..... [1][2] Mo. [8][6] Year

Quantity manufactured ..... 0 kg

Quantity imported ..... 0 kg

Quantity processed ..... 6740 kg

Year ending ..... [1][2] Mo. [8][5] Year

Quantity manufactured ..... 0 kg

Quantity imported ..... 0 kg

Quantity processed ..... 7126 kg

2.05 Specify the manner in which you manufactured the listed substance. Circle all appropriate process types.

CBI

[ ]

Continuous process ..... N/A 1

Semicontinuous process ..... N/A 2

Batch process ..... N/A 3

[ ] Mark (X) this box if you attach a continuation sheet.

2.06 Specify the manner in which you processed the listed substance. Circle all
CBI appropriate process types.

[ ]

Continuous process 1

Semicontinuous process 2

Batch process ..... (3)

2.07 State your facility's name-plate capacity for manufacturing or processing the listed substance. (If you are a batch manufacturer or batch processor, do not answer this
CBI question.)

[ ]

Manufacturing capacity ..... _____ kg/yr

Processing capacity ..... _____ kg/yr

2.08 If you intend to increase or decrease the quantity of the listed substance manufactured, imported, or processed at any time after your current corporate fiscal year, estimate the increase or decrease based upon the reporting year's production
CBI volume.

[ ]

	Manufacturing Quantity (kg)	Importing Quantity (kg)	Processing Quantity (kg)
Amount of increase			
Amount of decrease			

[ ] Mark (X) this box if you attach a continuation sheet.

2.09 For the three largest volume manufacturing or processing process types involving the listed substance, specify the number of days you manufactured or processed the listed substance during the reporting year. Also specify the average number of hours per day each process type was operated. (If only one or two operations are involved, list those.)

CBI

[ ]

	Days/Year	Average Hours/Day
Process Type #1 (The process type involving the largest quantity of the listed substance.)		
Manufactured		
Processed	112	3
Process Type #2 (The process type involving the 2nd largest quantity of the listed substance.)		
Manufactured		
Processed	20	3
Process Type #3 (The process type involving the 3rd largest quantity of the listed substance.)		
Manufactured		
Processed		

2.10 State the maximum daily inventory and average monthly inventory of the listed substance that was stored on-site during the reporting year in the form of a bulk chemical.

CBI

[ ]

Maximum daily inventory	2500	kg
Average monthly inventory	1020	kg

[ ] Mark (X) this box if you attach a continuation sheet.

2.11 Related Product Types -- List any byproducts, coproducts, or impurities present with the listed substance in concentrations greater than 0.1 percent as it is manufactured, imported, or processed. The source of byproducts, coproducts, or impurities means the source from which the byproducts, coproducts, or impurities are made or introduced into the product (e.g., carryover from raw material, reaction product, etc.).

CBI

[ ]

CAS No.	Chemical Name	Byproduct, Coproduct or Impurity[1]	Concentration (%) (specify ± % precision)	Source of Byproducts, Coproducts, or Impurities
UK	UK	UK	UK	UK

[1]Use the following codes to designate byproduct, coproduct, or impurity:

B = Byproduct
C = Coproduct
I = Impurity

[ ] Mark (X) this box if you attach a continuation sheet.

2.12 Existing Product Types -- List all existing product types which you manufactured, imported, or processed using the listed substance during the reporting year. List the quantity of listed substance you use for each product type as a percentage of the total volume of listed substance used during the reporting year. Also list the CBI quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to [ ] the instructions for further explanation and an example.)

a. Product Types[1]	b. % of Quantity Manufactured, Imported, or Processed	c. % of Quantity Used Captively On-Site	d. Type of End-Users[2]
L	100	100	I

[1]Use the following codes to designate product types:

A = Solvent
B = Synthetic reactant
C = Catalyst/Initiator/Accelerator/Sensitizer
D = Inhibitor/Stabilizer/Scavenger/Antioxidant
E = Analytical reagent
F = Chelator/Coagulant/Sequestrant
G = Cleanser/Detergent/Degreaser
H = Lubricant/Friction modifier/Antiwear agent
I = Surfactant/Emulsifier
J = Flame retardant
K = Coating/Binder/Adhesive and additives
L = Moldable/Castable/Rubber and additives
M = Plasticizer
N = Dye/Pigment/Colorant/Ink and additives
O = Photographic/Reprographic chemical and additives
P = Electrodeposition/Plating chemicals
Q = Fuel and fuel additives
R = Explosive chemicals and additives
S = Fragrance/Flavor chemicals
T = Pollution control chemicals
U = Functional fluids and additives
V = Metal alloy and additives
W = Rheological modifier
X = Other (specify) _____

[2]Use the following codes to designate the type of end-users:

I = Industrial
CM = Commercial
CS = Consumer
H = Other (specify) _____

[ ] Mark (X) this box if you attach a continuation sheet.

2.13 Expected Product Types -- Identify all product types which you expect to manufacture, import, or process using the listed substance at any time after your current corporate fiscal year. For each use, specify the quantity you expect to manufacture, import, or process for each use as a percentage of the total volume of listed substance used during the reporting year. Also list the quantity of listed substance used captively on-site as a percentage of the value listed under column b., and the types of end-users for each product type. (Refer to the instructions for further explanation and an example.)

CBI

[ ]

a. Product Types[1]	b. % of Quantity Manufactured, Imported, or Processed	c. % of Quantity Used Captively On-Site	d. Type of End-Users[2]
L	100	100	I

[1]Use the following codes to designate product types:

A = Solvent
B = Synthetic reactant
C = Catalyst/Initiator/Accelerator/Sensitizer
D = Inhibitor/Stabilizer/Scavenger/Antioxidant
E = Analytical reagent
F = Chelator/Coagulant/Sequestrant
G = Cleanser/Detergent/Degreaser
H = Lubricant/Friction modifier/Antiwear agent
I = Surfactant/Emulsifier
J = Flame retardant
K = Coating/Binder/Adhesive and additives
L = Moldable/Castable/Rubber and additives
M = Plasticizer
N = Dye/Pigment/Colorant/Ink and additives
O = Photographic/Reprographic chemical and additives
P = Electrodeposition/Plating chemicals
Q = Fuel and fuel additives
R = Explosive chemicals and additives
S = Fragrance/Flavor chemicals
T = Pollution control chemicals
U = Functional fluids and additives
V = Metal alloy and additives
W = Rheological modifier
X = Other (specify) _____

[2]Use the following codes to designate the type of end-users:

I = Industrial
CM = Commercial
CS = Consumer
H = Other (specify) _____

[ ] Mark (X) this box if you attach a continuation sheet.

2.14 CBI [ ] Final Product -- Complete the following table for each type of final product manufactured, imported, or processed at your facility that contains the listed substance other than as an impurity.

a. Product Type[1]	b. Final Product's Physical Form[2]	c. Average % Composition of Listed Substance in Final Product	d. Type of End-Users[3]
L	F1	Less than .1%	I

[1]Use the following codes to designate product types:

A = Solvent
B = Synthetic reactant
C = Catalyst/Initiator/Accelerator/Sensitizer
D = Inhibitor/Stabilizer/Scavenger/Antioxidant
E = Analytical reagent
F = Chelator/Coagulant/Sequestrant
G = Cleanser/Detergent/Degreaser
H = Lubricant/Friction modifier/Antiwear agent
I = Surfactant/Emulsifier
J = Flame retardant
K = Coating/Binder/Adhesive and additives
L = Moldable/Castable/Rubber and additives
M = Plasticizer
N = Dye/Pigment/Colorant/Ink and additives
O = Photographic/Reprographic chemical and additives
P = Electrodeposition/Plating chemicals
Q = Fuel and fuel additives
R = Explosive chemicals and additives
S = Fragrance/Flavor chemicals
T = Pollution control chemicals
U = Functional fluids and additives
V = Metal alloy and additives
W = Rheological modifier
X = Other (specify) _____

[2]Use the following codes to designate the final product's physical form:

A = Gas
B = Liquid
C = Aqueous solution
D = Paste
E = Slurry
F1 = Powder
F2 = Crystalline solid
F3 = Granules
F4 = Other solid
G = Gel
H = Other (specify) _____

[3]Use the following codes to designate the type of end-users:

I = Industrial
CM = Commercial
CS = Consumer
H = Other (specify) _____

[ ] Mark (X) this box if you attach a continuation sheet.

2.15 Circle all applicable modes of transportation used to deliver bulk shipments of the listed substance to off-site customers.

CBI

[ ] Truck ..... N/A 1

Railcar ..... N/A 2

Barge, Vessel ..... N/A 3

Pipeline ..... N/A 4

Plane ..... N/A 5

Other (specify) N/A 6

2.16 Customer Use -- Estimate the quantity of the listed substance used by your customers or prepared by your customers during the reporting year for use under each category of end use listed (i-iv).

CBI

[ ]

Category of End Use

i. Industrial Products

Chemical or mixture ..... N/A kg/yr

Article ..... N/A kg/yr

ii. Commercial Products

Chemical or mixture ..... N/A kg/yr

Article ..... N/A kg/yr

iii. Consumer Products

Chemical or mixture ..... N/A kg/yr

Article ..... N/A kg/yr

iv. Other

Distribution (excluding export) ..... N/A kg/yr

Export ..... N/A kg/yr

Quantity of substance consumed as reactant ..... N/A kg/yr

Unknown customer uses ..... N/A kg/yr

[ ] Mark (X) this box if you attach a continuation sheet.

SECTION 3 PROCESSOR RAW MATERIAL IDENTIFICATION

PART A GENERAL DATA

3.01 Specify the quantity purchased and the average price paid for the listed substance for each major source of supply listed. Product trades are treated as purchases.
CBI The average price is the market value of the product that was traded for the listed substance.
[ ]

Source of Supply	Quantity (kg)	Average Price ($/kg)
The listed substance was manufactured on-site.		
The listed substance was transferred from a different company site.		
The listed substance was purchased directly from a manufacturer or importer.		
The listed substance was purchased from a distributor or repackager.	6749	$ 2.71
The listed substance was purchased from a mixture producer.		

3.02 Circle all applicable modes of transportation used to deliver the listed substance to your facility.
CBI
[ ]

Truck ..... (1)
Railcar 2
Barge, Vessel 3
Pipeline 4
Plane 5
Other (specify) _____ 6

[ ] Mark (X) this box if you attach a continuation sheet.

3.03 CBI

a. Circle all applicable containers used to transport the listed substance to your facility.

[ ]

Bags 1

Boxes 2

Free standing tank cylinders 3

Tank rail cars 4

Hopper cars 5

Tank trucks 6

Hopper trucks 7

Drums ..... (8)

Pipeline 9

Other (specify) _____ 10

b. If the listed substance is transported in pressurized tank cylinders, tank rail cars, or tank trucks, state the pressure of the tanks.

Tank cylinders ..... _____ mmHg

Tank rail cars ..... _____ mmHg

Tank trucks ..... _____ mmHg

[ ] Mark (X) this box if you attach a continuation sheet.

PART B RAW MATERIAL IN THE FORM OF A MIXTURE

3.04 If you obtain the listed substance in the form of a mixture, list the trade name(s) of the mixture, the name of its supplier(s) or manufacturer(s), an estimate of the CBI average percent composition by weight of the listed substance in the mixture, and the amount of mixture processed during the reporting year.

[ ] N.A. 26471-62-5 = 80/20 MIXTURE

Trade Name	Supplier or Manufacturer	Average % Composition by Weight (specify ± % precision)	Amount Processed (kg/yr)
TDI 80- 20	Monson Chem	100% 26471-62-5	
(A Mixture	Of 20% + 1.0	2,·6 Toluene Diisocyanate	
and 80% + 1.0)			

[ ] Mark (X) this box if you attach a continuation sheet.

PART C RAW MATERIAL VOLUME

3.05 CBI [ ] State the quantity of the listed substance used as a raw material during the reporting year in the form of a class I chemical, class II chemical, or polymer, and the percent composition, by weight, of the listed substance.

	Quantity Used (kg/yr)	% Composition by Weight of Listed Substance in Raw Material (specify ± % precision)
Class I chemical	6794	99.7 + UK
Class II chemical		
Polymer		

[ ] Mark (X) this box if you attach a continuation sheet.

SECTION 4 PHYSICAL/CHEMICAL PROPERTIES

General Instructions:

If you are reporting on a mixture as defined in the glossary, reply to questions in Section 4 that are inappropriate to mixtures by stating "NA -- mixture."

For questions 4.06-4.15, if you possess any hazard warning statement, label, MSDS, or other notice that addresses the information requested, you may submit a copy or reasonable facsimile in lieu of answering those questions which it addresses.

PART A PHYSICAL/CHEMICAL DATA SUMMARY

4.01 Specify the percent purity for the three major[1] technical grade(s) of the listed substance as it is manufactured, imported, or processed. Measure the purity of the substance in the final product form for manufacturing activities, at the time you import the substance, or at the point you begin to process the substance.

CBI

[ ]

	Manufacture	Import	Process
Technical grade #1	_____ % purity	_____ % purity	99.7 % purity
Technical grade #2	_____ % purity	_____ % purity	_____ % purity
Technical grade #3	_____ % purity	_____ % purity	_____ % purity

[1]Major = Greatest quantity of listed substance manufactured, imported or processed.

4.02 Submit your most recently updated Material Safety Data Sheet (MSDS) for the listed substance, and for every formulation containing the listed substance. If you possess an MSDS that you developed and an MSDS developed by a different source, submit your version. Indicate whether at least one MSDS has been submitted by circling the appropriate response.

Yes ..... (1)

No 2

Indicate whether the MSDS was developed by your company or by a different source.

Your company ..... (1)

Another source ..... (2)

[XX] Mark (X) this box if you attach a continuation sheet.

4.03 Submit a copy or reasonable facsimile of any hazard information (other than an MSDS) that is provided to your customers/users regarding the listed substance or any formulation containing the listed substance. Indicate whether this information has been submitted by circling the appropriate response.

Yes 1

No ..... (2)

4.04 For each activity that uses the listed substance, circle all the applicable number(s) corresponding to each physical state of the listed substance during the activity listed. Physical states for importing and processing activities are determined at the time you import or begin to process the listed substance. Physical states for manufacturing, storage, disposal and transport activities are determined using the final state of the product.

CBI

[ ]

	Physical State				
Activity	Solid	Slurry	Liquid	Liquified Gas	Gas
Manufacture	(1)	2	3	4	5
Import	1	2	3	4	5
Process	1	2	(3)	4	5
Store	(1)	2	3	4	5
Dispose	1	2	3	4	5
Transport	(1)	2	3	4	5

[ ] Mark (X) this box if you attach a continuation sheet.

4.05 Particle Size -- If the listed substance exists in particulate form during any of the following activities, indicate for each applicable physical state the size and the percentage distribution of the listed substance by activity. Do not include particles ≥10 microns in diameter. Measure the physical state and particle sizes for importing and processing activities at the time you import or begin to process the listed substance. Measure the physical state and particle sizes for manufacturing storage, disposal and transport activities using the final state of the product.

CBI

[ ]

Physical State		Manufacture	Import	Process	Store	Dispose	Transport
Dust	<1 micron			N/A			
	1 to <5 microns			N/A			
	5 to <10 microns			N/A			
Powder	<1 micron			N/A			
	1 to <5 microns			N/A			
	5 to <10 microns			N/A			
Fiber	<1 micron			N/A			
	1 to <5 microns			N/A			
	5 to <10 microns			N/A			
Aerosol	<1 micron			N/A			
	1 to <5 microns			N/A			
	5 to <10 microns			N/A			

[ ] Mark (X) this box if you attach a continuation sheet.

SECTION 5 ENVIRONMENTAL FATE

PART A RATE CONSTANTS AND TRANSFORMATION PRODUCTS

5.01 Indicate the rate constants for the following transformation processes.

a. Photolysis:

Absorption spectrum coefficient (peak) .... U K (1/M cm) at _____ nm

Reaction quantum yield, ϕ ..... U K at _____ nm

Direct photolysis rate constant, k_p, at ... U K 1/hr _____ latitude

b. Oxidation constants at 25°C:

For $^1O_2$ (singlet oxygen), k_{ox} ..... U K 1/M hr

For RO_2 (peroxy radical), k_{ox} ..... U K 1/M hr

c. Five-day biochemical oxygen demand, BOD_5 ... U K mg/l

d. Biotransformation rate constant:

For bacterial transformation in water, k_b... U K 1/hr

Specify culture ..... U K

e. Hydrolysis rate constants:

For base-promoted process, k_B ..... U K 1/M hr

For acid-promoted process, k_A ..... U K 1/M hr

For neutral process, k_N ..... U K 1/hr

f. Chemical reduction rate (specify conditions) U K

g. Other (such as spontaneous degradation) ... U K

[ ] Mark (X) this box if you attach a continuation sheet.

PART B PARTITION COEFFICIENTS

5.02 a. Specify the half-life of the listed substance in the following media.

Media	Half-life (specify units)
Groundwater	U K
Atmosphere	U K
Surface water	U K
Soil	

b. Identify the listed substance's known transformation products that have a half-life greater than 24 hours.

CAS No.	Name	Half-life (specify units)	Media
U K			in
			in
			in
			in

5.03 Specify the octanol-water partition coefficient, K_{ow} ... U K at 25°C

Method of calculation or determination ..... U K

5.04 Specify the soil-water partition coefficient, K_d ..... U K at 25°C

Soil type ..... U K

5.05 Specify the organic carbon-water partition coefficient, K_{oc} ..... U K at 25°C

5.06 Specify the Henry's Law Constant, H ..... U K atm-m^3/mole

[ ] Mark (X) this box if you attach a continuation sheet.

5.07 List the bioconcentration factor (BCF) of the listed substance, the species for which it was determined, and the type of test used in deriving the BCF.

Bioconcentration Factor	Species	Test[1]
U K	U K	UK

[1]Use the following codes to designate the type of test:

F = Flowthrough
S = Static

[ ] Mark (X) this box if you attach a continuation sheet.

6.04 For each market listed below, state the quantity sold and the total sales value of
CBI the listed substance sold or transferred in bulk during the reporting year.

[ ]

Market	Quantity Sold or Transferred (kg/yr)	Total Sales Value ($/yr)
Retail sales		
Distribution -- Wholesalers		
Distribution -- Retailers		
Intra-company transfer		
Repackagers		
Mixture producers		
Article producers		
Other chemical manufacturers or processors		
Exporters		
Other (specify)		
_____		

6.05 Substitutes -- List all known commercially feasible substitutes that you know exist for the listed substance and state the cost of each substitute. A commercially feasible substitute is one which is economically and technologically feasible to use
CBI in your current operation, and which results in a final product with comparable performance in its end uses.

[ ]

Substitute	Cost ($/kg)
U K	

[ ] Mark (X) this box if you attach a continuation sheet.

SECTION 7 MANUFACTURING AND PROCESSING INFORMATION

General Instructions:

For questions 7.04-7.06, provide a separate response for each process block flow diagram provided in questions 7.01, 7.02, and 7.03. Identify the process type from which the information is extracted.

PART A MANUFACTURING AND PROCESSING PROCESS TYPE DESCRIPTION

7.01 In accordance with the instructions, provide a process block flow diagram showing the major (greatest volume) process type involving the listed substance.

CBI

[ ] Process type ..... BATCH ADAPHAX 758 + 759



[ ] Mark (X) this box if you attach a continuation sheet.

7.03 In accordance with the instructions, provide a process block flow diagram showing all process emission streams and emission points that contain the listed substance and which, if combined, would total at least 90 percent of all facility emissions if not treated before emission into the environment. If all such emissions are released from one process type, provide a process block flow diagram using the instructions for question 7.01. If all such emissions are released from more than one process type, provide a process block flow diagram showing each process type as a separate block.

CBI

[ ] Process type ..... Batch - see block diagram at 7.01

Vapors of listed substance are drawn through a caustic scrubber.

CBI

[ ] Process type ..... BATCH ADAPHAX 75E + 75F



[ ] Mark (X) this box if you attach a continuation sheet.

7.04 Describe the typical equipment types for each unit operation identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... Batch

Unit Operation ID Number	Typical Equipment Type	Operating Temperature Range (°C)	Operating Pressure Range (mm Hg)	Vessel Composition
7.1	Portable Drum	Ambient	Atmospheric	
	Scale	Ambient	Atmospheric	
7.2	Mixing Kettle	Ambient	Atmospheric	Steel
7.3	Tray Approx 3x4	Ambient	Atmospheric	Aluminum
7.4	Hood	Ambient	Atmospheric	Fiberglass
7.5	Scrubber	Ambient	Atmospheric	Fiberglass
7.6	Attritor Mills	Ambient	Atmospheric	Steel
7.7	Ducts + Cyclones	Ambient	Atmospheric	S. Steel
7.8	Drum Packer	Ambient	Atmospheric	+ Fiberglass Steel

[ ] Mark (X) this box if you attach a continuation sheet.

7.05 **Describe each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type.**

CBI

[ ] Process type ..... Batch

Process Stream ID Code	Process Stream Description	Physical State[1]	Stream Flow (kg/yr)
7.1	Ingredients Added From Drums	OL	
7.2	Reaction Kettle	OL	6462
7.3	AL. Curing tray	OL-SO	6462
7.4	Air + Odor	G U	
7.5	10% Caustic Scrubber	A L	
7.6	Attritor Mills	S O	6462
7.7	Ducts + S.S. Cyclones	S O	6462
7.8	Drum Packer	S O	6462

[1]Use the following codes to designate the physical state for each process stream:

GC = Gas (condensible at ambient temperature and pressure)
GU = Gas (uncondensible at ambient temperature and pressure)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

[ ] Mark (X) this box if you attach a continuation sheet.

7.06 Characterize each process stream identified in your process block flow diagram(s). If a process block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the CBI instructions for further explanation and an example.)

[ ] Process type ..... Batch Adaphax 758

a. Process Stream ID Code	b. Known Compounds[1]	c. Concentrations[2,3] (% or ppm)	d. Other Expected Compounds	e. Estimated Concentrations (% or ppm)
7.1	Castor Oil	57.5 %		
+	DEHP	28.7 %		
7.2	TDI- 80-20	13.8%		
7.3	Adaphax 758			
7.6	Polyurethane Resin	71.3%		
7.7	DEHP	28.7%		
7.8				
7.4	U K	U K		

7.06 continued below

[ ] Mark (X) this box if you attach a continuation sheet.

7.06 (continued)

[1]For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column b. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
1	N/A	
	N/A	
	N/A	
2	N/A	
	N/A	
	N/A	
3	N/A	
	N/A	
	N/A	
4	N/A	
	N/A	
	N/A	
5	N/A	
	N/A	
	N/A	

[2]Use the following codes to designate how the concentration was determined:

A = Analytical result
E = Engineering judgement/calculation

[3]Use the following codes to designate how the concentration was measured:

V = Volume
W = Weight

[ ] Mark (X) this box if you attach a continuation sheet.

PART A RESIDUAL TREATMENT PROCESS DESCRIPTION

8.01 In accordance with the instructions, provide a residual treatment block flow diagram which describes the treatment process used for residuals identified in question 7.01.

CBI

[ ] Process type ..... BATCH _ NO RESIDUALS

[ ] Mark (X) this box if you attach a continuation sheet.

PART B RESIDUAL GENERATION AND CHARACTERIZATION

8.05 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI

[ ] Process type ..... BATCH NO RESIDUALS

a. Stream ID Code	b. Type of Hazardous Waste[1]	c. Physical State of Residual[2]	d. Known Compounds[3]	e. Concentrations (% or ppm)[4,5,6]	f. Other Expected Compounds	g. Estimated Concentrations (% or ppm)

8.05 continued below

[ ] Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

[1]Use the following codes to designate the type of hazardous waste:

I = Ignitable
C = Corrosive
R = Reactive
E = EP toxic
T = Toxic
H = Acutely hazardous

[2]Use the following codes to designate the physical state of the residual:

GC = Gas (condensible at ambient temperature and pressure)
GU = Gas (uncondensible at ambient temperature and pressure)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

8.05 continued below

[ ] Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

[3]For each additive package introduced into a process stream, specify the compounds that are present in each additive package, and the concentration of each component. Assign an additive package number to each additive package and list this number in column d. (Refer to the instructions for further explanation and an example. Refer to the glossary for the definition of additive package.)

Additive Package Number	Components of Additive Package	Concentrations (% or ppm)
1	N/A	
	N/A	
	N/A	
2	N/A	
	N/A	
	N/A	
3	N/A	
	N/A	
	N/A	
4	N/A	
	N/A	
	N/A	
5	N/A	
	N/A	
	N/A	

[4]Use the following codes to designate how the concentration was determined:

A = Analytical result
E = Engineering judgement/calculation

8.05 continued below

[ ] Mark (X) this box if you attach a continuation sheet.

8.05 (continued)

[5]Use the following codes to designate how the concentration was measured:

V = Volume
W = Weight

[6]Specify the analytical test methods used and their detection limits in the table below. Assign a code to each test method used and list those codes in column e.

Code	Method	Detection Limit (± ug/l)
1	N/A	
2	N/A	
3	N/A	
4	N/A	
5	N/A	
6	N/A	

[ ] Mark (X) this box if you attach a continuation sheet.

8.06 Characterize each process stream identified in your residual treatment block flow diagram(s). If a residual treatment block flow diagram is provided for more than one process type, photocopy this question and complete it separately for each process type. (Refer to the instructions for further explanation and an example.)

CBI

[ ] Process type ..... BATCH NO RESIDUALS

a. Stream ID Code	b. Waste Description Code[1]	c. Management Method Code[2]	d. Residual Quantities (kg/yr)	e. Management of Residual (%) On-Site	e. Management of Residual (%) Off-Site	f. Costs for Off-Site Management (per kg)	g. Changes in Management Methods

[1]Use the codes provided in Exhibit 8-1 to designate the waste descriptions

[2]Use the codes provided in Exhibit 8-2 to designate the management methods

[ ] Mark (X) this box if you attach a continuation sheet.

8.22 Describe the combustion chamber design parameters for each of the three largest (by capacity) incinerators that are used on-site to burn the residuals identified in your process block or residual treatment block flow diagram(s).

CBI

[ ]

Incinerator	Combustion Chamber Temperature (°C)		Location of Temperature Monitor		Residence Time In Combustion Chamber (seconds)	
	Primary	Secondary	Primary	Secondary	Primary	Secondary
1						
2						
3						

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

Yes 1

No 2

8.23 Complete the following table for the three largest (by capacity) incinerators that are used on-site to burn the residuals identified in your process block or residual treatment block flow diagram(s).

CBI

[ ]

Incinerator	Air Pollution Control Device[1]	Types of Emissions Data Available
1 N/A		
2 N/A		
3 N/A		

Indicate if Office of Solid Waste survey has been submitted in lieu of response by circling the appropriate response.

Yes 1

No 2

[1]Use the following codes to designate the air pollution control device:

S = Scrubber (include type of scrubber in parenthesis)
E = Electrostatic precipitator
O = Other (specify) _____

[ ] Mark (X) this box if you attach a continuation sheet.

PART A EMPLOYMENT AND POTENTIAL EXPOSURE PROFILE

9.01 Mark (X) the appropriate column to indicate whether your company maintains records on the following data elements for hourly and salaried workers. Specify for each data element the year in which you began maintaining records and the number of years the CBI records for that data element are maintained. (Refer to the instructions for further explanation and an example.)

[ ]

Data Element	Data are Maintained for: Hourly Workers	Salaried Workers	Year in Which Data Collection Began	Number of Years Records Are Maintained
Date of hire	X	X	1968	T+ 8 *
Age at hire	X	X	1968	T + 8
Work history of individual ** before employment at your facility	X	X	1968	T+8
Sex	N/A	N/A	N/A	N/A
Race	N/A	N/A	N/A	N/A
Job titles	X	X	X	T+8
Start date for each job title	X	X	X	T+ 8
End date for each job title	X	X	X	T + 8
Work area industrial hygiene monitoring data	X	X	1985	PERMANENT
Personal employee monitoring data	X	X	1985	PERMANENT
Employee medical history	X	X	1968	T + 8
Employee smoking history	N/A	N/A	N/A	N/A
Accident history	X	X	1968	T + 8
Retirement date	X	X	1968	T + 8
Termination date	X	X	1968	T + 8
Vital status of retirees	X	X	1985	PERMANENT
Cause of death data	X	X	1985	PERMANENT

* T= Termination
** = If on employee application

[ ] Mark (X) this box if you attach a continuation sheet.

9.02 In accordance with the instructions, complete the following table for each activity in which you engage.

CBI

[ ]

a. Activity	b. Process Category	c. Yearly Quantity (kg)	d. Total Workers	e. Total Worker-Hours
Manufacture of the listed substance	Enclosed	N/A	N/A	N/A
	Controlled Release	N/A	N/A	N/A
	Open	N/A	N/A	N/A
On-site use as reactant	Enclosed	N/A	N/A	N/A
	Controlled Release	N/A	N/A	N/A
	Open	N/A	N/A	N/A
On-site use as nonreactant	Enclosed	N/A	N/A	N/A
	Controlled Release	N/A	N/A	N/A
	Open	N/A	N/A	N/A
On-site preparation of products	Enclosed	N/A	N/A	N/A
	Controlled Release	N/A	N/A	N/A
	Open			

[ ] Mark (X) this box if you attach a continuation sheet.

9.03 Provide a descriptive job title for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance.

CBI

[ ]

Labor Category	Descriptive Job Title
A	Sr. Operator, White Department
B	Operator, White Department
C	
D	
E	
F	
G	
H	
I	
J	

[ ] Mark (X) this box if you attach a continuation sheet.

9.04 In accordance with the instructions, provide your process block flow diagram(s) and indicate associated work areas.

CBI

[ ] Process type ..... BATCH ADAPMAX 7SE + 7S



Work Areas

[ ] Mark (X) this box if you attach a continuation sheet.

9.05 Describe the various work area(s) shown in question 9.04 that encompass workers who may potentially come in contact with or be exposed to the listed substance. Add any additional areas not shown in the process block flow diagram in question 7.01 or 7.02. Photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... _____

Work Area ID	Description of Work Areas and Worker Activities
1	Workers weigh and add TDI to reactor
2	Workers drain reactor to curing trays
3	Workers cut and place product (solid)
4	in chute to grinding
5	
6	
7	
8	
9	
10	

[ ] Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area ..... (1)

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance[1]	Average Length of Exposure Per Day[2]	Number of Days per Year Exposed
A	1	INHALATION	OL	A	66

[1]Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensible at ambient temperature and pressure)
GU = Gas (uncondensible at ambient temperature and pressure; includes fumes, vapors, etc.)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

[2]Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
B = Greater than 15 minutes, but not exceeding 1 hour
C = Greater than one hour, but not exceeding 2 hours
D = Greater than 2 hours, but not exceeding 4 hours
E = Greater than 4 hours, but not exceeding 8 hours
F = Greater than 8 hours

[ ] Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area .....

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance[1]	Average Length of Exposure Per Day[2]	Number of Days per Year Exposed
A	1	INHALATION	OL	A	66
B	2	INHALATION	OL	A	66

[1]Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensible at ambient temperature and pressure)
GU = Gas (uncondensible at ambient temperature and pressure; includes fumes, vapors, etc.)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

[2]Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
B = Greater than 15 minutes, but not exceeding 1 hour
C = Greater than one hour, but not exceeding 2 hours
D = Greater than 2 hours, but not exceeding 4 hours
E = Greater than 4 hours, but not exceeding 8 hours
F = Greater than 8 hours

[ ] Mark (X) this box if you attach a continuation sheet.

9.06 Complete the following table for each work area identified in question 9.05, and for each labor category at your facility that encompasses workers who may potentially come in contact with or be exposed to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area ..... (3)

Labor Category	Number of Workers Exposed	Mode of Exposure (e.g., direct skin contact)	Physical State of Listed Substance[1]	Average Length of Exposure Per Day[2]	Number of Days per Year Exposed
B	2	INHALATION	SO	B	66

[1]Use the following codes to designate the physical state of the listed substance at the point of exposure:

GC = Gas (condensible at ambient temperature and pressure)
GU = Gas (uncondensible at ambient temperature and pressure; includes fumes, vapors, etc.)
SO = Solid
SY = Sludge or slurry
AL = Aqueous liquid
OL = Organic liquid
IL = Immiscible liquid (specify phases, e.g., 90% water, 10% toluene)

[2]Use the following codes to designate average length of exposure per day:

A = 15 minutes or less
B = Greater than 15 minutes, but not exceeding 1 hour
C = Greater than one hour, but not exceeding 2 hours
D = Greater than 2 hours, but not exceeding 4 hours
E = Greater than 4 hours, but not exceeding 8 hours
F = Greater than 8 hours

[ ] Mark (X) this box if you attach a continuation sheet.

9.07 For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area 1

Labor Category	8-hour TWA Exposure Level (ppm, mg/m^3, other-specify)	15-Minute Peak Exposure Level (ppm, mg/m^3, other-specify)
A	.0008 PPM	0.16 PPM

[ ] Mark (X) this box if you attach a continuation sheet.

9.07 For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area .. (2) .....

Labor Category	8-hour TWA Exposure Level (ppm, mg/m^3, other-specify)	15-Minute Peak Exposure Level (ppm, mg/m^3, other-specify)
A	.0008 ppm	UK
B	.0008 ppm	UK

[ ] Mark (X) this box if you attach a continuation sheet.

9.07 For each labor category represented in question 9.06, indicate the 8-hour Time Weighted Average (TWA) exposure levels and the 15-minute peak exposure levels. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area ..... (13)

Labor Category	8-hour TWA Exposure Level (ppm, mg/m^3, other-specify)	15-Minute Peak Exposure Level (ppm, mg/m^3, other-specify)
B	< .0008 ppm	U.K.

[ ] Mark (X) this box if you attach a continuation sheet.

PART B WORK PLACE MONITORING PROGRAM

9.08 If you monitor worker exposure to the listed substance, complete the following table.

CBI

[ ]

Sample/Test	Work Area ID	Testing Frequency (per year)	Number of Samples (per test)	Who Samples[1]	Analyzed In-House (Y/N)	Number of Years Records Maintained
Personal breathing zone	1, 2, + 3	1	7-8	D	Y	PERMANENT
General work area (air)						
Wipe samples						
Adhesive patches						
Blood samples						
Urine samples						
Respiratory samples						
Allergy tests						
Other (specify) _____						
Other (specify) _____						
Other (specify) _____						

[1]Use the following codes to designate who takes the monitoring samples:

A = Plant industrial hygienist
B = Insurance carrier
C = OSHA consultant
D = Other (specify) Chemical Group Industrial Hygienist

[ ] Mark (X) this box if you attach a continuation sheet.

9.09 For each sample type identified in question 9.08, describe the type of sampling and analytical methodology used for each type of sample.

CBI

[ ]	Sample Type	Sampling and Analytical Methodology
	Personal Breathing Zone	Personal air monitoring pump with glass fiber filter treated with 1- (2- pyridyl) - piper azine sample and analyzed by liquid chromatography
	General work area	Air monitoring pump and glass fiber filter treaten with ~~(2- pyridyl) piperazine and sampling and~~ analyzed by liquid chromatography

9.10 If you conduct personal and/or ambient air monitoring for the listed substance, specify the following information for each equipment type used.

CBI

[ ]	Equipment Type[1]	Detection Limit[2]	Manufacturer	Averaging Time (hr)	Model Number
	D	Depends on the ~~vol sample of air~~	filter (millipore) ~~pump (Gilian)~~	8HR ~~1/4 HR~~	HFS-113A

[1]Use the following codes to designate personal air monitoring equipment types:

A = Passive dosimeter
B = Detector tube
C = Charcoal filtration tube with pump
D = Other (specify) Glass fiber filter treaten with 1-(2-pyridyl)- piperazine with Gilian model 113 A pump.

Use the following codes to designate ambient air monitoring equipment types:

E = Stationary monitors located within work area
F = Stationary monitors located within facility
G = Stationary monitors located at plant boundary
H = Mobile monitoring equipment (specify) _____
I = Other (specify) _____

[2]Use the following codes to designate detection limit units:

A = ppm
B = Fibers/cubic centimeter (f/cc)
C = Micrograms/cubic meter (μ/m^3)

[ ] Mark (X) this box if you attach a continuation sheet.

9.11 If you conduct routine medical tests for monitoring the health effects of exposure to the listed substance, specify the type and frequency of the tests.

CBI

[ ]	Test Description	Frequency (weekly, monthly, yearly, etc.)
	N/A	

[ ] Mark (X) this box if you attach a continuation sheet.

PART C ENGINEERING CONTROLS

9.12 Describe the engineering controls that you use to reduce or eliminate worker exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... _____

Work area ..1..... _____

Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:				
Local exhaust	20 +	U K	Y	1986
General dilution				
Other (specify)				
Vessel emission controls	11 Years	1978		
Mechanical loading or packaging equipment				
Other (specify)				

* Caustic Scrubber

[X] Mark (X) this box if you attach a continuation sheet.

PART C ENGINEERING CONTROLS

9.12 Describe the engineering controls that you use to reduce or eliminate worker exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... Batch

Work area 2

Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:				
Local exhaust				
General dilution				
Other (specify)				
Caustic Scrubber	11 Yrs.	1978	N	
Vessel emission controls				
Mechanical loading or packaging equipment				
Other (specify)				

[ ] Mark (X) this box if you attach a continuation sheet.

PART C ENGINEERING CONTROLS

9.12 Describe the engineering controls that you use to reduce or eliminate worker exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... Batch

Work area 3

Engineering Controls	Used (Y/N)	Year Installed	Upgraded (Y/N)	Year Upgraded
Ventilation:				
Local exhaust				
General dilution				
Other (specify)				
Vessel emission controls				
Mechanical loading or packaging equipment				
Other (specify)				
Caustic Scrubber	11 Yrs	1978		

[ ] Mark (X) this box if you attach a continuation sheet.

9.13 Describe all equipment or process modifications you have made within the 3 years prior to the reporting year that have resulted in a reduction of worker exposure to the listed substance. For each equipment or process modification described, state the percentage reduction in exposure that resulted. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area .(1).....

Equipment or Process Modification	Reduction in Worker Exposure Per Year (%)
LOCAL ELEPHANT TRUNK EXHAUST DUCTED TO THE CAUSTIC SCRUBBER.	U.K.

[ ] Mark (X) this box if you attach a continuation sheet.

PART D PERSONAL PROTECTIVE AND SAFETY EQUIPMENT

9.14 Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... BATCH

Work area 1 1

Equipment Types	Wear or Use (Y/N)
Respirators	N
Safety goggles/glasses	Y
Face shields	N
Coveralls	N
Bib aprons	N
Chemical-resistant gloves	N
Other (specify)	

[ ] Mark (X) this box if you attach a continuation sheet.

PART D PERSONAL PROTECTIVE AND SAFETY EQUIPMENT

9.14 Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... Batch

Work area 2 2

Equipment Types	Wear or Use (Y/N)
Respirators	N
Safety goggles/glasses	Y
Face shields	N
Coveralls	N
Bib aprons	N
Chemical-resistant gloves	N
Other (specify)	

[ ] Mark (X) this box if you attach a continuation sheet.

PART D PERSONAL PROTECTIVE AND SAFETY EQUIPMENT

9.14 Describe the personal protective and safety equipment that your workers wear or use in each work area in order to reduce or eliminate their exposure to the listed substance. Photocopy this question and complete it separately for each process type and work area.

CBI

[ ] Process type ..... Batch

Work area 3 3

Equipment Types	Wear or Use (Y/N)
Respirators	N
Safety goggles/glasses	Y
Face shields	N
Coveralls	N
Bib aprons	N
Chemical-resistant gloves	N
Other (specify)	

[ ] Mark (X) this box if you attach a continuation sheet.

9.15 If workers use respirators when working with the listed substance, specify for each process type, the work areas where the respirators are used, the type of respirators used, the average usage, whether or not the respirators were fit tested, and the type and frequency of the fit tests. Photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... BATCH

Work Area	Respirator Type	Average Usage[1]	Fit Tested (Y/N)	Type of Fit Test[2]	Frequency of Fit Tests (per year)
1	FULL FACE RESP.	E	Y	PL	1

[1]Use the following codes to designate average usage:

A = Daily
B = Weekly
C = Monthly
D = Once a year
E = Other (specify) Twice/ Week

[2]Use the following codes to designate the type of fit test:

QL = Qualitative
QT = Quantitative

[ ] Mark (X) this box if you attach a continuation sheet.

PART E WORK PRACTICES

9.19 Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this CBI question and complete it separately for each process type and work area.

[ ]

Process type ..... BATCH

Work area (3) ..... SAFETY TRAINING

MSDS SHEETS - WORKER MONITORING

9.20 Indicate (X) how often you perform each housekeeping task used to clean up routine leaks or spills of the listed substance. Photocopy this question and complete it separately for each process type and work area.

Process type ..... BATCH

Work area (3) .....

Housekeeping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
Sweeping	N.A.			
Vacuuming				
Water flushing of floors	NA*			
Other (specify)				

* LISTED SUBSTANCE DOES NOT SPILL THIS AREA

[ ] Mark (X) this box if you attach a continuation sheet.

9.19 Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this CBI question and complete it separately for each process type and work area.

[ ]

Process type ..... BATCH

Work area (2) ..... SAFETY TRAINING

MSDS SHEETS - WORKER MONITORING

9.20 Indicate (X) how often you perform each housekeeping task used to clean up routine leaks or spills of the listed substance. Photocopy this question and complete it separately for each process type and work area.

Process type ..... BATCH

Work area 2

Housekeeping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
Sweeping	X			
Vacuuming				
Water flushing of floors	X			
Other (specify)				

[ ] Mark (X) this box if you attach a continuation sheet.

9.19 Describe all of the work practices and administrative controls used to reduce or eliminate worker exposure to the listed substance (e.g., restrict entrance only to authorized workers, mark areas with warning signs, insure worker detection and monitoring practices, provide worker training programs, etc.). Photocopy this question and complete it separately for each process type and work area.

CBI

[ ]

Process type ..... BATCH

Work area (1) ..... ~~SAFETY~~ TRAINING

MSDS SHEETS - DRUM STORAGE AREA MARKED WITH WARNING SIGNS - WORKER MONITORING

9.20 Indicate (X) how often you perform each housekeeping task used to clean up routine leaks or spills of the listed substance. Photocopy this question and complete it separately for each process type and work area.

Process type ..... BATCH

Work area ..(1).....

Housekeeping Tasks	Less Than Once Per Day	1-2 Times Per Day	3-4 Times Per Day	More Than 4 Times Per Day
Sweeping	X			
Vacuuming				
Water flushing of floors	X			
Other (specify)				

[ ] Mark (X) this box if you attach a continuation sheet.

9.21 Do you have a written medical action plan for responding to routine or emergency exposure to the listed substance?

Routine exposure

Yes 1

No 2

Emergency exposure

Yes 1

No 2

If yes, where are copies of the plan maintained?

Routine exposure: _____

Emergency exposure: _____

9.22 Do you have a written leak and spill cleanup plan that addresses the listed substance? Circle the appropriate response.

Yes 1

No ..... (2)

If yes, where are copies of the plan maintained? _____

Has this plan been coordinated with state or local government response organizations? Circle the appropriate response.

Yes 1

No 2

9.23 Who is responsible for monitoring worker safety at your facility? Circle the appropriate response.

Plant safety specialist 1

Insurance carrier 2

OSHA consultant 3

Other (specify) _____ 4

[ ] Mark (X) this box if you attach a continuation sheet.

SECTION 10 ENVIRONMENTAL RELEASE

General Instructions:

Complete Part E (questions 10.23-10.35) for each non-routine release involving the listed substance that occurred during the reporting year. Report on all releases that are equal to or greater than the listed substance's reportable quantity value, RQ, unless the release is federally permitted as defined in 42 U.S.C. 9601, or is specifically excluded under the definition of release as defined in 40 CFR 302.3(22). Reportable quantities are codified in 40 CFR Part 302. If the listed substance is not a hazardous substance under the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and, thus, does not have an RQ, then report releases that exceed 2,270 kg. If such a substance however, is designated as a CERCLA hazardous substance, then report those releases that are equal to or greater than the RQ. The facility may have answered these questions or similar questions under the Agency's Accidental Release Information Program and may already have this information readily available. Assign a number to each release and use this number throughout this part to identify the release. Releases over more than a 24-hour period are not single releases, i.e., the release of a chemical substance equal to or greater than an RQ must be reported as a separate release for each 24-hour period the release exceeds the RQ.

For questions 10.25-10.35, answer the questions for each release identified in question 10.23. Photocopy these questions and complete them separately for each release.

PART A GENERAL INFORMATION

10.01 Where is your facility located? Circle all appropriate responses.

CBI

[ ] Industrial area 1

Urban area 2

Residential area 3

Agricultural area 4

Rural area 5

Adjacent to a park or a recreational area 6

Within 1 mile of a navigable waterway 7

Within 1 mile of a school, university, hospital, or nursing home facility 8

Within 1 mile of a non-navigable waterway 9

Other (specify) _____ 10

[ ] Mark (X) this box if you attach a continuation sheet.

10.02 Specify the exact location of your facility (from central point where process unit is located) in terms of latitude and longitude or Universal Transverse Mercader (UTM) coordinates.

Latitude ..... 41 ° 2 ' 31 "

Longitude ..... 73 ° 31 ' 44 "

UTM coordinates ..... Zone _____, Northing _____, Easting _____

10.03 If you monitor meteorological conditions in the vicinity of your facility, provide the following information.

Average annual precipitation ..... _____ inches/year

Predominant wind direction ..... _____

10.04 Indicate the depth to groundwater below your facility.

Depth to groundwater ..... _____ meters

10.05 For each on-site activity listed, indicate (Y/N/NA) all routine releases of the listed substance to the environment. (Refer to the instructions for a definition of Y, N, and NA.)

CBI

[ ]

On-Site Activity	Environmental Release		
	Air	Water	Land
Manufacturing			
Importing			
Processing	N	N	N
Otherwise used			
Product or residual storage			
Disposal			
Transport			

[ ] Mark (X) this box if you attach a continuation sheet.

10.06 Provide the following information for the listed substance and specify the level of precision for each item. (Refer to the instructions for further explanation and an example.)

CBI

[ ]

Quantity discharged to the air	0 N/A	kg/yr ± ___	%
Quantity discharged in wastewaters	0 N/A	kg/yr ± ___	%
Quantity managed as other waste in on-site treatment, storage, or disposal units	0 N/A	kg/yr ± ___	%
Quantity managed as other waste in off-site treatment, storage, or disposal units	N/A	kg/yr ± ___	%

[ ] Mark (X) this box if you attach a continuation sheet.

10.08 Describe the control technologies used to minimize release of the listed substance for each process stream containing the listed substance as identified in your process block or residual treatment block flow diagram(s). Photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... BATCH

Stream ID Code	Control Technology	Percent Efficiency
7.5	Caustic Scrubber	UK *

* Assumed to be 100% since listed substance is destroyed immediately upon contact with water.

[ ] Mark (X) this box if you attach a continuation sheet.

PART B RELEASE TO AIR

10.09 Point Source Emissions -- Identify each emission point source containing the listed substance in terms of a Stream ID Code as identified in your process block or residual treatment block flow diagram(s), and provide a description of each point source. Do not include raw material and product storage vents, or fugitive emission sources (e.g., equipment leaks). Photocopy this question and complete it separately for each process type.

CBI

[ ]

Process type ..... Batch

Point Source ID Code	Description of Emission Point Source
N/A	N/A

[ ] Mark (X) this box if you attach a continuation sheet.

[ ] Mark (X) this box if you attach a continuation sheet.

10.10 Emission Characteristics - - Characterize the emissions for each Point Source ID Code identified in question 10.09 by completing the following table.

CBI

[ ]

Point Source ID Code	Physical State[1]	Average Emissions (kg/day)	Frequency[2] (days/yr)	Duration[3] (min/day)	Average Emission Factor[4]	Maximum Emission Rate (kg/min)	Maximum Emission Rate Frequency (events/yr)	Maximum Emission Rate Duration (min/event)
N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A

[1]Use the following codes to designate physical state at the point of release:
G = Gas; V = Vapor; P = Particulate; A = Aerosol; 0 = Other (specify) _____

[2]Frequency of emission at any level of emission

[3]Duration of emission at any level of emission

[4]Average Emission Factor — Provide estimated (± 25 percent) emission factor (kg of emission per kg of production of listed substance)

10.11 Stack Parameters -- Identify the stack parameters for each Point Source ID Code identified in question 10.09 by completing the following table.

CBI

[ ]

Point Source ID Code	Stack Height(m)	Stack Inner Diameter (at outlet) (m)	Exhaust Temperature (°C)	Emission Exit Velocity (m/sec)	Building Height(m)[1]	Building Width(m)[2]	Vent Type[3]
N/A							

[1]Height of attached or adjacent building

[2]Width of attached or adjacent building

[3]Use the following codes to designate vent type:

H = Horizontal
V = Vertical

[ ] Mark (X) this box if you attach a continuation sheet.

10.12 If the listed substance is emitted in particulate form, indicate the particle size distribution for each Point Source ID Code identified in question 10.09. Photocopy this question and complete it separately for each emission point source.

CBI

[ ]

Point source ID code ..... N/A

Size Range (microns)	Mass Fraction (% ± % precision)
< 1	
≥ 1 to < 10	
≥ 10 to < 30	
≥ 30 to < 50	
≥ 50 to < 100	
≥ 100 to < 500	
≥ 500	

Total = 100%

[ ] Mark (X) this box if you attach a continuation sheet.

PART C FUGITIVE EMISSIONS

10.13 Equipment Leaks -- Complete the following table by providing the number of equipment types listed which are exposed to the listed substance and which are in service according to the specified weight percent of the listed substance passing through the component. Do this for each process type identified in your process block or residual treatment block flow diagram(s). Do not include equipment types that are not exposed to the listed substance. If this is a batch or intermittently operated process, give an overall percentage of time per year that the process type is exposed to the listed substance. Photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... Batch

Percentage of time per year that the listed substance is exposed to this process type ..... 18 %

Equipment Type	Number of Components in Service by Weight Percent of Listed Substance in Process Stream					
	Less than 5%	5-10%	11-25%	26-75%	76-99%	Greater than 99%
Pump seals[1]						
Packed	N/A	N/A	N/A	N/A	N/A	N/A
Mechanical	N/A	N/A	N/A	N/A	N/A	N/A
Double mechanical[2]	N/A	N/A	N/A	N/A	N/A	N/A
Compressor seals[1]	N/A	N/A	N/A	N/A	N/A	N/A
Flanges	N/A	N/A	N/A	N/A	N/A	N/A
Valves						
Gas[3]	N/A	N/A	N/A	N/A	N/A	N/A
Liquid						18%
Pressure relief devices[4] (Gas or vapor only)	N/A	N/A	N/A	N/A	N/A	N/A
Sample connections						
Gas	N/A	N/A	N/A	N/A	N/A	N/A
Liquid	N/A	N/A	N/A	N/A	N/A	N/A
Open-ended lines[5] (e.g., purge, vent)						
Gas	N/A	N/A	N/A	N/A	N/A	N/A
Liquid	N/A	N/A	N/A	N/A	N/A	18%

[1]List the number of pump and compressor seals, rather than the number of pumps or compressors

10.13 continued on next page

[ ] Mark (X) this box if you attach a continuation sheet.

10.13 (continued)

[2]If double mechanical seals are operated with the barrier (B) fluid at a pressure greater than the pump stuffing box pressure and/or equipped with a sensor (S) that will detect failure of the seal system, the barrier fluid system, or both, indicate with a "B" and/or an "S", respectively

[3]Conditions existing in the valve during normal operation

[4]Report all pressure relief devices in service, including those equipped with control devices

[5]Lines closed during normal operation that would be used during maintenance operations

10.14 Pressure Relief Devices with Controls -- Complete the following table for those pressure relief devices identified in 10.13 to indicate which pressure relief devices in service are controlled. If a pressure relief device is not controlled, enter "None" under column c.

CBI

[ ]

a. Number of Pressure Relief Devices	b. Percent Chemical in Vessel[1]	c. Control Device	d. Estimated Control Efficiency[2]
N/A			

[1]Refer to the table in question 10.13 and record the percent range given under the heading entitled "Number of Components in Service by Weight Percent of Listed Substance" (e.g., <5%, 5-10%, 11-25%, etc.)

[2]The EPA assigns a control efficiency of 100 percent for equipment leaks controlled with rupture discs under normal operating conditions. The EPA assigns a control efficiency of 98 percent for emissions routed to a flare under normal operating conditions

[ ] Mark (X) this box if you attach a continuation sheet.

10.15 Equipment Leak Detection -- If a formal leak detection and repair program is in place, complete the following table regarding those leak detection and repair procedures. Photocopy this question and complete it separately for each process type.

CBI

[ ] Process type ..... N/A

Equipment Type	Leak Detection Concentration (ppm or mg/m^3) Measured at ____ Inches from Source	Detection Device[1]	Frequency of Leak Detection (per year)	Repairs Initiated (days after detection)	Repairs Completed (days after initiated)
Pump seals					
Packed					
Mechanical					
Double mechanical					
Compressor seals					
Flanges					
Valves					
Gas					
Liquid					
Pressure relief devices (gas or vapor only)					
Sample connections					
Gas					
Liquid					
Open-ended lines					
Gas					
Liquid					

[1]Use the following codes to designate detection device:

POVA = Portable organic vapor analyzer
FPM = Fixed point monitoring
O = Other (specify) _____

[ ] Mark (X) this box if you attach a continuation sheet.

Listed substance (raw materials) is stored in closed 55 gallon drums. Product has no listed substance.

10.16 Raw Material, Intermediate and Product Storage Emissions - - Complete the following table by providing the information on each liquid raw material, intermediate, and product storage vessel containing the listed substance as identified in your process block or residual treatment block flow diagram(s).

CBI

[ ]

Vessel Type[1]	Floating Roof Seals[2]	Composition of Stored Materials[3]	Throughput (liters per year)	Vessel Filling Rate (gpm)	Vessel Filling Duration (min)	Vessel Inner Diameter (m)	Vessel Height (m)	Operating Vessel Volume (l)	Vessel Emission Controls[4]	Design Flow Rate[5]	Vent Diameter (cm)	Control Efficiency (%)	Basis for Estimate[6]

[1]Use the following codes to designate vessel type:

F = Fixed roof
CIF = Contact internal floating roof
NCIF = Noncontact internal floating roof
EFR = External floating roof
P = Pressure vessel (indicate pressure rating)
H = Horizontal
U = Underground

[2]Use the following codes to designate floating roof seals:

MS1 = Mechanical shoe, primary
MS2 = Shoe-mounted secondary
MS2R = Rim-mounted, secondary
LM1 = Liquid-mounted resilient filled seal, primary
LM2 = Rim-mounted shield
LMW = Weather shield
VM1 = Vapor mounted resilient filled seal, primary
VM2 = Rim-mounted secondary
VMW = Weather shield

[3]Indicate weight percent of the listed substance. Include the total volatile organic content in parenthesis

[4]Other than floating roofs

[5]Gas/vapor flow rate the emission control device was designed to handle (specify flow rate units)

[6]Use the following codes to designate basis for estimate of control efficiency:

C = Calculations
S = Sampling

[ ] Mark (X) this box if you attach a continuation sheet.

PART E NON-ROUTINE RELEASES

No non routine releases.

10.23 Indicate the date and time when the release occurred and when the release ceased or was stopped. If there were more than six releases, attach a continuation sheet and list all releases.

Release	Date Started	Time (am/pm)	Date Stopped	Time (am/pm)
1	N/A			
2				
3				
4				
5				
6				

10.24 Specify the weather conditions at the time of each release.

Release	Wind Speed (km/hr)	Wind Direction	Humidity (%)	Temperature (°C)	Precipitation (Y/N)
1	N/A				
2					
3					
4					
5					
6					

[ ] Mark (X) this box if you attach a continuation sheet.

APPENDIX I: List of Continuation Sheets

Attach continuation sheets for sections of this form and optional information after this page. In column 1, clearly identify the continuation sheet by listing the question number to which it relates. In column 2, enter the inclusive page numbers of the continuation sheet for each question number.

Question Number (1)	Continuation Sheet Page Numbers (2)
4.02	
4.03	
4.03	

[ ] Mark (X) this box if you attach a continuation sheet.

Olin MATERIAL SAFETY DATA 4.02

OCEAN® Network
EMERGENCY PHONE 1-800-OLIN-911

SECTION I - IDENTIFICATION

MSDS FILE 563

CHEMICAL NAME & SYNONYMS Toluene Diisocyanate 80-20		
CHEMICAL FAMILY Isocyanate	**FORMULA** $C_9H_6N_2O_2$	**PRODUCT** TDI 80-20
DESCRIPTION Clear water white to pale yellow liquid with sharp pungent odor		**CAS NO.** 26471-62-5

SECTION II - NORMAL HANDLING PROCEDURES

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Harmful if swallowed. Avoid contact with eyes, skin or clothing. Upon contact with skin or eyes, wash off with water. Avoid breathing mist or vapor. Protect against physical damage. Store in a cool, dry, well-ventilated place, away from areas where a fire hazard may be acute. Outside or detached storage is preferred. Blanket storage tanks with inert gas (nitrogen) or dry air. Separate from oxidizing materials.

PROTECTIVE EQUIPMENT	VENTILATION REQUIREMENTS
EYES Goggles **GLOVES** Rubber, NBR or PVA **OTHER** Coveralls, impervious footwear	As required to keep airborne concentrations below TLV

SECTION III - HAZARDOUS INGREDIENTS

BASIC MATERIAL	OSHA PEL	LD50	LC50	SIGNIFICANT EFFECTS
*Toluene-2,4-diisocyanate (80%) CAS No.: 584-84-9	0.005 ppm TWA 0.02 ppm STEL	5.8 g/kg (rat)	10 ppm/4 hrs (mouse)	Skin, eye, mucous membrane irritation. Pulmonary irritant. Allergic sensitization to skin and respiratory tract. May cause asthma attacks.
*Toluene-2,6-diisocyanate(20%),CAS No.:91-08-7	None established	No data	11 ppm/4 hrs-mouse	Irritation

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT 270°F COC **METHOD**	**OSHA CLASSIFICATION** Not Regulated (Ignitable)	**FLAMMABLE EXPLOSIVE LIMIT**	**LOWER** 0.9%	**UPPER** 9.5%

EXTINGUISHING MEDIA Water, carbon dioxide or dry chemical. Use water to keep the exposed containers cool.

SPECIAL FIRE HAZARD & FIRE FIGHTING PROCEDURES Use NIOSH/MSHA approved positive pressure self-contained breathing apparatus when any material is involved in a fire.

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
0.005 ppm TWA, 0.02 ppm STEL - 2,4 TDI (ACGIH 1987-88)

SYMPTOMS OF OVER EXPOSURE May cause irritation to eyes, throat, lungs, stomach, skin. Allergic sensitization to skin and respiratory tract. May cause asthma attacks

EMERGENCY FIRST-AID PROCEDURES

SKIN Immediately flush thoroughly with water for 15 minutes, call a physician.

EYES Immediately flush thoroughly with water for 15 minutes, call a physician.

INGESTION Immediately drink large quantities of water to dilute.

INHALATION Immediately remove victim to fresh air. Call a physician.

PRODUCT CODE 898859 CHEMICAL NAME TDI 80-20

SECTION VI - TOXICOLOGY (PRODUCT)

ACUTE ORAL LD 50 5.8 g/kg (rats). Harmful if swallowed.
ACUTE DERMAL LD 50
> 2 g/kg (rabbits)
ACUTE INHALATION LC 50
10 ppm/4 hrs (mouse)

CARCINOGENICITY Oral Exposure-Positive NTP Bioassay
MUTAGENICITY Not known to be mutagenic
EYE IRRITATION Irritation and/or burns
PRIMARY SKIN IRRITATION
Irritation and/or burns

PRINCIPAL ROUTES OF ABSORPTION
Inhalation, dermal contact

EFFECTS OF ACUTE EXPOSURE May cause irritation to lungs, eyes, throat, stomach, skin. Allergic sensitization of skin and respiratory tract. Corneal injury may occur.

EFFECTS OF CHRONIC EXPOSURE Damage/allergic sensitization to lungs. Inhalation studies indicate not carcinogenic. Carcinogenic risk from industrial use is not significant.

SECTION VII - SPILL AND LEAKAGE PROCEDURES (CONTROL PROCEDURES)

ACTION FOR MATERIAL RELEASE OR SPILL
Wear NIOSH/MSHA approved positive pressure supplied air respirator. Follow OSHA regulations for respirator use (see 29 CFR 1910.134). Wear goggles, coveralls and impervious gloves and boots. Add dry non-combustible absorbent, sweep up material and place in an approved DOT container. Add an equal amount of neutralizing solution to the container (90-95% water, 5-10% ammonia). Clean remaining surfaces with neutralizing solution and add this to container. Isolate container in a well-ventilated place and do not seal for 24 hrs. Ammonia vapors may be generated until solution is neutralized. Wash all contaminated clothing before reuse. In the event of a large spill use the telephone number shown on the front of this sheet.

TRANSPORTATION EMERGENCY, CONTACT CHEMTREC 800-424-9300

THE MIXTURE OR TRADE NAME PRODUCT HEREIN CONTAINS A TOXIC CHEMICAL(S) SUBJECT TO THE REPORTING REQUIREMENTS OF SECTION 313 OF TITLE III OF THE SUPERFUND AMENDMENTS AND REAUTHORIZATION ACT OF 1986 AND 40 CFR PART 372. THE SARA 313 CHEMICALS ARE LISTED IN SECTION III AND ARE INDICATED BY AN ASTERISK (*).

SECTION VIII - SHIPPING DATA

D.O.T. Toluene diisocyanate Poison B UN 2078

SECTION IX - REACTIVITY DATA

STABLE X **UNSTABLE AT** ____ **C** ____ **F**

HAZARDOUS POLYMERIZATION	**MAY OCCUR** X
	WILL NOT OCCUR

CONDITIONS TO AVOID
Water or incompatible materials in a closed system, excess heat
INCOMPATIBILITY(MATERIAL TO AVOID)
Acids, bases and alcohols, surface active materials
HAZARDOUS DECOMPOSITION PRODUCTS
Carbon monoxide, nitrogen oxides, hydrogen cyanide

SECTION X - PHYSICAL DATA

MELTING POINT 53-56°F	**VAPOR PRESSURE** .01mmHg, 20°C	**VOLATILES** No data
BOILING POINT 484°F	**SOLUBILITY IN WATER** Insoluble	**EVAPORATION RATE** No data
SPECIFIC GRAVITY(H2O=1) 1.22	**PH** No data	**VAPOR DENSITY(AIR=1)** 6.0

INFORMATION: FURNISHED TO

ATTN: DEPT HANDLING MATL SAFETY DATA SHEETS
MR. DOWNEY
AMERICAN CYANAMID
205 MCGEE AVE.

STAMFORD CT06902

FURNISHED BY **DATE** APRIL 28, 1989

Olin MSDS Control Group
(203) 356-3449

Olin CORPORATION
120 Long Ridge Road, Stamford, Connecticut 06904
OCEAN® Network
EMERGENCY PHONE 1-800-OLIN-911

CYANAMID

4.03

MATERIAL SAFETY DATA

MSDS NO. 0452-02
CAS NO. 67700-43-0
DATE: 04/29/87

PRODUCT IDENTIFICATION

TRADE NAME:	**ADAPHAX® 758 Polyurethane**
SYNONYMS:	Urethane resin
CHEMICAL FAMILY:	Urethane
MOLECULAR FORMULA:	Polymer
MOLECULAR WGT.:	Polymer

WARNING

WARNING! HARMFUL IF INHALED

CHRONIC HAZARD WARNINGS

CONTAINS MATERIAL WHICH CAUSED CANCER IN LABORATORY ANIMAL TESTS

OSHA REGULATED COMPONENTS

COMPONENT	CAS. NO.	%	TWA/CEILING	REFERENCE
Di-2-ethylhexyl-phthalate	000117-81-7	28.75	5 mg/M3	OSHA/ACGIH IARC/NTP

NFPA HAZARD RATING

Fire 0
Health 1 0 Reactivity
\- Special

FIRE: Materials that will not burn.
HEALTH: Materials which on exposure would cause irritation but only minor residual injury even if no treatment is given
REACTIVITY: Materials which in themselves are normally stable, even under fire exposure conditions, and which are not reactive with water.

HEALTH HAZARD INFORMATION

EFFECTS OF OVEREXPOSURE:

Overexposure to this material is not likely to cause significant acute toxic effects.
Di-2-ethylhexylphthalate caused liver cancer in male and female rats and mice fed a diet of 6,000 or 12,000 ppm and 3,000 or 6,000 ppm, respectively for 2 years.
Di-2-ethylhexylphthalate caused changes in the liver cells of mice and rats at higher concentrations and were not found at lower dose levels. If these changes do not occur, then it is unlikely that tumors will be formed. Also these liver changes seem to be unique to rodents as shown by Di-2-ethylhexylphthalate metabolism studies comparing rats and primates.
Di-2-ethylhexylphthalate was nonmutagenic in the Ames assay, and did not induce chromosomal changes in human and animal cells.
Di-2-ethylhexylphthalate did induce a nondose-dependant, but significant increase in sister chromatid exchanges in Chinese hamster cells. A single i.p. dose of 12.7-25.5 g/kg induced a small but significant dominant lethal effect in male mice.

FIRST AID:

In case of skin contact, wash affected areas of skin with soap and water.
In case of eye contact, immediately irrigate with plenty of water for 15 minutes.

EMERGENCY PHONE: 201/835-3100

AMERICAN CYANAMID COMPANY, 1 CYANAMID PLAZA, WAYNE, NEW JERSEY 07470

If vapor or dust of this material is inhaled, remove from exposure. Administer oxygen if there is difficulty in breathing.

EXPOSURE CONTROL METHODS

Engineering controls are not usually necessary, if good hygiene practices are strictly followed. Before eating, drinking or smoking, wash face and hands thoroughly with soap and water. Wear the following as necessary to prevent skin contact: impervious gloves. For operations where eye or face contact can occur wear chemical splash-proof goggles. Where concentrations are below the PEL, no respiratory protection is required. For spills or leaks, such protection may be necessary. Where exposures exceed PEL use respirator approved by NIOSH for the material and level of exposure. See "GUIDE TO INDUSTRIAL RESPIRATORY PROTECTION" (NIOSH).

FIRE AND EXPLOSION HAZARD INFORMATION	FLASH POINT:	Not Applicable
	FLAMMABLE LIMITS (% BY VOL):	Not Applicable
	AUTOIGNITION TEMP:	Not Available
	DECOMPOSITION TEMP:	Not Available
	FIRE FIGHTING:	This material will not burn. Use an extinguishing media appropriate for the surrounding fire. Wear self-contained, positive pressure breathing apparatus.
REACTIVITY DATA	STABILITY: CONDITIONS TO AVOID:	Stable None known
	POLYMERIZATION: CONDITIONS TO AVOID:	Will Not Occur None known
	INCOMPATIBLE MATERIALS:	Strong oxidizing agents.
	HAZARDOUS DECOMPOSITION PRODUCTS:	Thermal decomposition or combustion may produce carbon monoxide and/or carbon dioxide.
PHYSICAL PROPERTIES	APPEARANCE AND ODOR:	White powder
	BOILING POINT:	Not Applicable
	MELTING POINT:	Not Applicable
	VAPOR PRESSURE:	Negligible at 20 C
	VAPOR DENSITY:	Negligible at 20 C
	% VOLATILE (BY VOL):	Not Applicable
	OCTANOL/H_2O PARTITION COEF.:	Not Applicable
	pH:	Not Applicable
	SATURATION IN AIR (BY VOL):	Not Available
	EVAPORATION RATE:	Not Applicable
	SOLUBILITY IN WATER:	Negligible

ADAPHAX® 758 Polyurethane

SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Sweep up spills and place in a waste disposal container. Flush area with water.

WASTE DISPOSAL

Disposal must be made in accordance with applicable governmental regulations.

SPECIAL PRECAUTIONS

HANDLING AND STORAGE/OTHER: Maintain good housekeeping to control dust accumulations.

D.O.T. SHIPPING INFORMATION

PROPER SHIPPING NAME:	HAZARDOUS SUBSTANCE, SOLID, N.O.S.
HAZARD CLASS:	ORM-E
UN/NA:	NA9188
D.O.T. HAZARDOUS SUBSTANCES:	(Reportable Quantity of Product) DI-2-ETHYLHEXYLPHTHALATE (3.5 lbs.-28.8%)
D.O.T. LABEL REQUIRED:	None

TSCA INFORMATION

This product is manufactured in compliance with all provisions of the Toxic Substances Control Act, 15 U.S.C.

ENVIRONMENTAL INFORMATION

The following components are defined as toxic chemicals subject to reporting requirements of Section 313 of Title III and of 40 CFR 372 or subject to other EPA regulations.

			SARA TITLE III				
COMPONENT	CAS. NO.	%	TPQ (lbs.)	RQ (lbs.)	S313	RCRA	TSCA 12B
Di-2-ethylhexyl-phthalate	000117-81-7	28.75	NONE	1	YES	U028	NO

PRODUCT CLASSIFICATION UNDER SECTION 311 OF SARA

ACUTE (N)	CHRONIC (Y)	FIRE (N)	REACTIVE (N)	PRESSURE (N)

Marvin A. Friedman, Ph.D., Director of Toxicology and Product Safety

CYANAMID

MATERIAL SAFETY DATA

MSDS NO. 3659-02
CAS NO. 67700-43-0
DATE: 04/29/87

PRODUCT IDENTIFICATION

TRADE NAME:	**ADAPHAX® 759 Polyurethane**
SYNONYMS:	Urethane resin
CHEMICAL FAMILY:	Urethane polymer
MOLECULAR FORMULA:	Polymer
MOLECULAR WGT.:	Polymer

WARNING

WARNING! HARMFUL IF INHALED

CHRONIC HAZARD WARNINGS

CONTAINS MATERIAL WHICH CAUSED CANCER IN LABORATORY ANIMAL TESTS

OSHA REGULATED COMPONENTS

COMPONENT	CAS. NO.	%	TWA/CEILING	REFERENCE
Di-2-ethylhexyl-phthalate	000117-81-7	15.07	5 mg/M3	OSHA/ACGIH IARC/NTP

NFPA HAZARD RATING

Fire
0
Health 1 0 Reactivity
-
Special

FIRE: Materials that will not burn.
HEALTH: Materials which on exposure would cause irritation but only minor residual injury even if no treatment is given
REACTIVITY: Materials which in themselves are normally stable, even under fire exposure conditions, and which are not reactive with water.

HEALTH HAZARD INFORMATION

EFFECTS OF OVEREXPOSURE:

Overexposure to this material is not likely to cause significant acute toxic effects.
Di-2-ethylhexylphthalate caused liver cancer in male and female rats and mice fed a diet of 6,000 or 12,000 ppm and 3,000 or 6,000 ppm, respectively for 2 years.
Di-2-ethylhexylphthalate caused changes in the liver cells of mice and rats at higher concentrations and were not found at lower dose levels. If these changes do not occur, then it is unlikely that tumors will be formed. Also these liver changes seem to be unique to rodents as shown by Di-2-ethylhexylphthalate metabolism studies comparing rats and primates.
Di-2-ethylhexylphthalate was nonmutagenic in the Ames assay, and did not induce chromosomal changes in human and animal cells.
Di-2-ethylhexylphthalate did induce a nondose-dependant, but significant increase in sister chromatid exchanges in Chinese hamster cells. A single i.p. dose of 12.7-25.5 g/kg induced a small but significant dominant lethal effect in male mice.

FIRST AID:

In case of skin contact, wash affected areas of skin with soap and water.
In case of eye contact, immediately irrigate with plenty of water for 15 minutes.

EMERGENCY PHONE: 201/835-3100

AMERICAN CYANAMID COMPANY, 1 CYANAMID PLAZA, WAYNE, NEW JERSEY 07470

If vapor or dust of this material is inhaled, remove from exposure. Administer oxygen if there is difficulty in breathing.

EXPOSURE CONTROL METHODS

Engineering controls are not usually necessary, if good hygiene practices are strictly followed. Before eating, drinking or smoking, wash face and hands thoroughly with soap and water. Wear the following as necessary to prevent skin contact: impervious gloves. For operations where eye or face contact can occur wear chemical splash-proof goggles. Where concentrations are below the PEL, no respiratory protection is required. For spills or leaks, such protection may be necessary. Where exposures exceed PEL use respirator approved by NIOSH for the material and level of exposure. See "GUIDE TO INDUSTRIAL RESPIRATORY PROTECTION" (NIOSH).

FIRE AND EXPLOSION HAZARD INFORMATION	FLASH POINT:	Not Applicable
	FLAMMABLE LIMITS (% BY VOL):	Not Applicable
	AUTOIGNITION TEMP:	Not Available
	DECOMPOSITION TEMP:	Not Available
	FIRE FIGHTING:	This material will not burn. Use an extinguishing media appropriate for the surrounding fire. Wear self-contained, positive pressure breathing apparatus.
REACTIVITY DATA	STABILITY:	Stable
	CONDITIONS TO AVOID:	None known
	POLYMERIZATION:	Will Not Occur
	CONDITIONS TO AVOID:	None known
	INCOMPATIBLE MATERIALS:	Strong oxidizing agents.
	HAZARDOUS DECOMPOSITION PRODUCTS:	Thermal decomposition or combustion may produce carbon monoxide and/or carbon dioxide.
PHYSICAL PROPERTIES	APPEARANCE AND ODOR:	White powder
	BOILING POINT:	Not Applicable
	MELTING POINT:	Not Applicable
	VAPOR PRESSURE:	Negligible at 20 C
	SPECIFIC GRAVITY:	1.01
	VAPOR DENSITY:	Negligible at 20 C
	% VOLATILE (BY VOL):	Not Applicable
	OCTANOL/H_2O PARTITION COEF.:	Not Applicable
	pH:	Not Applicable
	SATURATION IN AIR (BY VOL):	Not Available
	EVAPORATION RATE:	Not Applicable
	SOLUBILITY IN WATER:	Negligible

SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Sweep up spills and place in a waste disposal container. Flush area with water.

WASTE DISPOSAL

Disposal must be made in accordance with applicable governmental regulations.

SPECIAL PRECAUTIONS

HANDLING AND STORAGE/OTHER: Maintain good housekeeping to control dust accumulations.

D.O.T. SHIPPING INFORMATION

PROPER SHIPPING NAME:	HAZARDOUS SUBSTANCE, SOLID, N.O.S.
HAZARD CLASS:	ORM-E
UN/NA:	NA9188
D.O.T. HAZARDOUS SUBSTANCES:	(Reportable Quantity of Product) DI-2-ETHYLHEXYLPHTHALATE (6.4 lbs.-15.1%)
D.O.T. LABEL REQUIRED:	None

TSCA INFORMATION

This product is manufactured in compliance with all provisions of the Toxic Substances Control Act, 15 U.S.C.

ENVIRONMENTAL INFORMATION

The following components are defined as toxic chemicals subject to reporting requirements of Section 313 of Title III and of 40 CFR 372 or subject to other EPA regulations.

			SARA TITLE III				
COMPONENT	CAS. NO.	%	TPQ (lbs.)	RQ (lbs.)	S313	RCRA	TSCA 12B
Di-2-ethylhexyl-phthalate	000117-81-7	15.07	NONE	1	YES	U028	NO

PRODUCT CLASSIFICATION UNDER SECTION 311 OF SARA

ACUTE (N)	CHRONIC (Y)	FIRE (N)	REACTIVE (N)	PRESSURE (N)

Marvin A. Friedman, Ph.D., Director of Toxicology and Product Safety

CYANAMID

American Cyanamid Company
Stamford-Shippan Plant
Post Office Box 852
Stamford, CT 06904

FIRST CLASS MAIL

CYANAMID

American Cyanamid Company
STAMFORD - SHIPPAN PLANT
205 MAGEE AVENUE
STAMFORD, CT 06902

Document Processing Center
Office of Toxic Substances, TS-790
U.S. Environmental Protection Agency
401 M Street, S W
Washington, D C 20460

Attn: CAIR Reporting Office

NA 1115-01 Rev. 6-80 PRINTED IN U.S.A. 6-80

RETURN POSTAGE GUARANTEED

Fold at line over top of envelope to the right of the return address.

CERTIFIED

P 417 296 633

MAIL

Return Receipt Requested